

REPLACEMENT SHEET

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 1 of 11
S01.12-0979




Fig. 1

REPLACEMENT SHEET

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 2 of 11
S01.12-0979




Fig. 2




Fig. 3

REPLACEMENT SHEET

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 4 of 11
S01.12-0979




Fig. 4

REPLACEMENT SHEET

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 5 of 11
S01.12-0979




Fig. 5

Michael D. Mundt et al. Sheet 6 of 11
AIR BEARING SLIDER HAVING...
 Serial. No.: 10/608,700 S01.12-0979

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 6 of 11
S01.12-0979




Fig. 6

REPLACEMENT SHEET

Michael D. Mundt et al. Sheet 7 of 11
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700 S01.12-0979




Fig. 7




Fig. 8

REPLACEMENT SHEET

Michael D. Mundt et al.
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700

Sheet 8 of 11
S01.12-0979




Fig. 9




Fig. 10

REPLACEMENT SHEET

Michael D. Mundt et al. Sheet 9 of 11
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700 S01.12-0979




Fig. 11




Fig. 12

REPLACEMENT SHEET

Michael D. Mundt et al.
 AIR BEARING SLIDER HAVING...
 Serial. No.: 10/608,700

Sheet 10 of 11
 S01.12-0979




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17